SAFETY NOTICE

TO ALL USERS OF ANTENNA PRODUCTS CORPORATION SCE-2 SAFETY SLEEVE FALL PROTECTION DEVICE FEBRUARY 28, 2007, REVISED 12 MARCH, 2007

Antenna Products Corporation has discovered that under certain conditions the SCE-2 safety sleeves, part number 1000-1672-401 and 1000-0425-401, may fail to function as designed and may allow a climber to fall a distance sufficient to cause serious injuries or death. Antenna Products Corporation is issuing the following instructions to all users of the SCE-2 safety sleeves.

- All climbers must use a maximum 6 foot long shock absorbing Y lanyard compliant with ANSI Z359.1 while climbing. The lanyard should be attached to the climber's safety harness in accordance with the lanyard manufacturers instructions and one leg of the lanyard should be connected at all times to the ladder during ascent, descent and stationary activities while on the ladder.
- 2. The SCE-2 sleeve should be used in the normal manner supplemented by the Y lanyard as described above.

Antenna Products Corporation is currently working to the resolve the issue. When the issue is resolved and fully tested, Antenna Products Corporation will modify or replace all existing SCE-2 sleeves at no cost. Please fill out the modification / replacement form below and forward to Tammy Garland. Please contact either of the following with questions.

Contact	Phone Number	Email	Fax	
Tammy Garland	940-325-3301 x240	garland@antennaproducts.com	940-325-0716	
Richard Gilley	940-325-3301 x306	gilley@antennaproducts.com	940-325-0716	

Antenna Products Corporation apologizes for the inconvenience caused by this situation.

Company Name				
Address				
City		_ State	Zip	
Contact Name		Phone	<u>;</u>	
Contact Email				
Number of sleeves to return	Sleeve S/N			
Return Shipping Address				
City		_ State	Zip	
Shipping Markings (if any)				

Return To: Antenna Products Corporation Attn: Tammy Garland

> 101 S.E. 25th Avenue Mineral Wells, Texas 76067



